## FITNESS CERTIFICATE

To be fiiled by the Inspecting Officer (Asst. Engineer)
(Re: MMB / B / ER / 22)

1.	Name of the Officer	Suman Baruah (B.E. Civil)
2.	Name of the School	Mangaldai Maharshree Vidyalay, Mangaldai
3.	Location with name of Education District/ Sub. District	Mangaldai, Darrang
4.	Classification of Building as specified in column 4 of the application for fitness certificate and size.	Permanent Multistoried RCC Building
		GF - 12.945 X 32.190 X 3.350
		FF – 12.945 X 32.190 X 3.350
		SF - 12.945 X 32.190 X 3.350
		TF - 12.945 X 32.190 X 3.350
5.	Period for which the certificate is issued	2025-2026
6.	Nature of defects, if any	
	a) Foundation and basement	Nil.
	b) Superstructure	Nil
	c) Doors and Windows	Nil
	d) Wood work wrought and put-up	Nil
	e) Roof	Nil
	f) Flooring	Nil
	g) Miscellaneous (Cracks, etc.)	Nil
7.	Any major defects noticed which will render the building unsafe in any manner	Nil
8.	The Structure is sound for conducting Classes.	Yes
9.		Yes
	Note: 1. The stability of the structure should be examined exposure of flood etc. 2. Any additional observations if deseparately with this certificate.	also with reference to location, altitude, intensity of wind eemed necessary for the certificate may be furnished

## CERTIFICATE

certified that the school building was inspected by me on 25-03-2025 and found to be fit / unfit to conduct classes, for the period of April-2025-March 2026 for the reasons stated above.

Place: 25/03/2025

Er. Suman Baruah (Civil Engineer) TP/RTP/04/Engg(C).Dec/22/59

Civil Engineer